




An icon showing an L-shaped bracket inside a circle, next to a power drill with a diagonal line through it, indicating that a power drill should not be used for assembly.

A warning triangle icon with an exclamation mark inside.

An icon showing a rectangular block on a mat inside a circle, next to a crossed-out block with a diagonal line through it, indicating that the block should be placed on a soft surface.


A warning triangle icon with an exclamation mark inside.

A clock icon showing a time of 15 minutes.

15'

An icon of a person standing.



1

1  x 1	2  x 1	3  x 2
---	---	---

1 x 1





2 x 1







4 x 1

3 x 2

4  x 1	A  M8 x 16 x 20	B  x 1
---	---	---

1



2

