



RECOMENDACIONES

Recommandations - Consigli - Recomendações -
Aanbevelingen - Empfehlungen

ES

Los tacos y tornillos incluidos no son aptos para paredes de pladur.

EN

The included plugs and screws are not suitable for drywall.

DE

Die mitgelieferten Dübel und Schrauben sind nicht für Gipswände geeignet.

FR

Les chevilles et les vis fournies ne conviennent pas aux murs en placoplâtre.

IT

I tasselli e le viti in dotazione non sono adatti alle pareti in cartongesso.



NL

De meegeleverde pluggen en schroeven zijn niet geschikt voor gipswanden.

PT

As buchas e os parafusos incluídos não são adequados para paredes de pladur.

Tibi



























NO	Dim.		Col.-No	Qty
1	268	384	1	1
2	268	384	1	1
3	268	364	1	2
4	1602	384	1	1
5	1602	384	1	1
6	582	349	1	1
7	496	296	1	2
8	1580	280	1	1




60 min

FLY TYP-33



A1 X16  Ø8x36	B4 X16 	B5 X16  Ø15x12	G5 X16 	G20 X4 	G2 X1 
E1 X4  H=0	E2 X4  H=0	S1 X12 	D6 X8  USØ3,5x30	D10 X16  USØ3,5x13	G21 X2 
ZR1 X4 	OS3 X1 	KR2 X4 	D7 X6  USØ3x16	AM X2 	






1





2



3




4




$X=Y$ 90°



5





6



7



8



9

