



RECOMENDACIONES

Recommandations - Consigli - Recomendações -
Aanbevelingen - Empfehlungen

ES

Los tacos y tornillos incluidos no son aptos para paredes de pladur.

EN

The included plugs and screws are not suitable for drywall.

DE

Die mitgelieferten Dübel und Schrauben sind nicht für Gipswände geeignet.

FR

Les chevilles et les vis fournies ne conviennent pas aux murs en placoplâtre.

IT

I tasselli e le viti in dotazione non sono adatti alle pareti in cartongesso.

NL



De meegeleverde pluggen en schroeven zijn niet geschikt voor gipswanden.

PT


As buchas e os parafusos incluídos não são adequados para paredes de pladur.




TVAO501




A × 16




Φ 8 × 40



C × 2




D × 3




Φ 8 × 60



Φ 3.5 × 14



Φ 3.5 × 30



H × 4

I1




I2



Φ 3 × 14

I × 12











J × 1




Φ 20


K × 16




1



2




3




$D \times 3$ $F \times 12$

4




$A \times 8$ $B \times 8$ $H \times 4$ $G \times 8$ $K \times 8$

5




J×1

6




7






F×10 C×2

8



I1×12 I2×12

9



E×8 H×4