



TIRIG






Tools and materials required for assembly:

- Icon of a pencil, a marker, a tape measure, and a power drill.
- Warning symbol (triangle with exclamation mark).
- Icon of a clock.
- Time estimate: **20'**
- Icon of a person.
- Number of people: **1**


Assembly steps:

- Step 1: A rectangular block is shown being placed on a textured surface.
- Step 2: A second rectangular block is shown being placed on top of the first block.

A








A




x 1


1



2



!



4/5

3

