





An icon showing an L-shaped metal bracket on the left and a power drill with a diagonal line through it on the right, indicating that a power drill should not be used for assembly.	A warning triangle icon with an exclamation mark inside.	A clock icon showing a 30-minute duration.
An icon showing a rectangular cushion being placed on a base on the left, and a screw being inserted into the cushion on the right with a diagonal line through it, indicating that screws should not be used to secure the cushions.	A warning triangle icon with an exclamation mark inside.	An icon of a person, representing the number of people required for assembly.




30'

1

1/5





!



1

<p>A</p> <p>x 1</p>	<p>D</p> <p>x 4</p>	<p>E</p> <p>M5 x 20 x 16</p>	<p>G</p> <p>x 1</p>
---------------------	---------------------	--	---------------------





2

F




x 1



3

B





x 1


C



x 1



!



!

