
















- | | | |
|----------|--------|-------|
| A | 4x45 | x 8 |
| B | 1.4x25 | x 115 |
| C | 3x25 | x 92 |
| D | 3x13 | x 3 |
| E | 3x40 | x 64 |




№		PCS			
			mm	mm	mm
1		2	19	52	1055
2		12	19	52	572
3		4	19	52	278
4		2	19	46	1055
5		12	19	46	572
6		4	19	46	278
7		152	19	92	572
8		62	19	92	1055
9		152	19	92	278
10		80	19	92	188
11		26	19	92	198
12		21	19	92	1808
13		5	15	35	1808
14		2	30	40	1490
15		3	12	642	1926
16		1		92	1055
17		20		194	225
18		1		572	1135
19		3	15	35	1926
20		4	15	35	978
21		1		38	1218
22		1	38	38	1218
23		16	25	30	150
24		8	15	35	260
25		2		1000	1966
26		2			
27		1			
28		1			


1




2





3



4




C x10




27


D x2



5



6



7

