














- Montageanleitung
- Assembly instructions
- Notice de montage
- Montagehandleiding
- Návod na montáž
- Instrucțiune de montaj
- Navodila za namestitev
- Installationstruktioener

























1a






1b






2



3a








3b












4a








4b







5






6





7





9




1  
Pos. 10

2



24 h

1909-0



Kontrollbeleg  
Control Receipt

Prüfnummer/ Inspection number

---



Service  
Am Lindhövel 1  
59846 Sundern  
Deutschland / Germany / Allemagne / Duitsland



Allgemeine technische Probleme:  
Telefon 02935 / 96 53 444



E-Mail:  
onlineservice@schulte.de