

























Diagram illustrating assembly instructions and safety warnings:

- Warning 1:** A warning triangle with an exclamation mark is shown next to a box containing an L-shaped metal bracket and a crossed-out power drill icon, indicating that a power drill should not be used for this step.
- Warning 2:** A second warning triangle with an exclamation mark is shown next to a box containing a mattress and a crossed-out icon of a mattress being placed on a slatted base, indicating that the mattress should not be placed on the slatted base.
- Time:** A clock icon is shown next to the text "45'", indicating the estimated time for this step.
- Personnel:** An icon of a person is shown next to the number "2", indicating that two people are required for this step.

A	B	C	D	E	F
					
x 1	x 1	x 2	x 2	x 6	x 4



<p>G</p>  <p>x 4</p>	<p>H</p>  <p>x 1</p>	<p>1</p>  <p>M6 x 100</p> <p>x 6</p>	<p>2</p>  <p>M6 x 50</p> <p>x 16</p>
<p>3</p>  <p>M6 x 40</p> <p>x 28</p>	<p>4</p>  <p>M6 x 20</p> <p>x 8</p>	<p>5</p>  <p>M6 x 15</p> <p>x 8</p>	<p>6</p>  <p>M8 x 50</p> <p>x 8</p>
<p>7</p>  <p>x 6</p>	<p>8</p>  <p>x 30</p>	<p>9</p>  <p>x 30</p>	<p>10</p>  <p>M4 x 32</p> <p>x 12</p>
<p>11</p>  <p>M4</p> <p>x 1</p>	<p>12</p>  <p>M5</p> <p>x 1</p>	<p>13</p>  <p>x 4</p>	<p>14</p>  <p>x 6</p>


1 x 4

F




x 1

G




x 1

6





x 2

12




x 1




2

A




x 1

B




x 1

5




x 4

11





x 1



13





x 4







3 x 2




4







5

<p>2</p>  <p>M6 x 50</p> <p>x 8</p>	<p>8</p>  <p>x 8</p>	<p>9</p>  <p>x 8</p>	<p>11</p>  <p>M4</p> <p>x 1</p>
--	---	--	--



6

<p>D</p>  <p>x 2</p>	<p>5</p>  <p>M6 x 15</p> <p>x 4</p>	<p>11</p>  <p>M4</p> <p>x 1</p>
---	--	--



7 x 6

E





x 1

14




x 1




8

H



x 1


1





M6
x
100

x 6

7





x 6



9

3
M6
x
40
x 28



10

10
M4
x
32
x 12

