
















TEXAS




1299_101331
























<p>2</p>	 <p>VA-C7R X1</p>	 <p>PB1 X1</p>	 <p>CN-A33</p>	
-----------------	--	---	---	--



3				
	PB4 X1	VA-D45 X9	CN-A33	





4				
	VA-C7L X1	PB1 X1	CN-A33	








3

5				
	PB4 X1	VA-D45 X9	CN-A33	



6				
	VA-C5 X2	VA-D44 X2	CN-A33	



4

7



PB4
X1



VA-C11
X3











VA-C8
X3



VA-D44
X2






CN-A33






5

8



9




6

10



VA-31
X4










VA-C5
X2




VA-D44
X16




CN-A33




11



PB3L
X1



PB3M
X1






PB3R
X1



VA-D45
X6







CN-A33







12









VA-C5b
X2



13



14



15





PB2
X1



VA-D45
X2



CN-A33



16



VA-33
X2



VA-34
X1







VA-D19
X2



VA-D20
X1




VA-D50
X10



17



VA-35
X2










VA-D23
X1








VA-D17
X2












VA-D44
X22




18











19














20  **VA-B22**
X2











21	 VA-B22 X2	 VA-D21 X4	 PB6-B X2	 PPX3 X4	 VA-D44 X8	 CN-A33	
----	---	---	--	---	---	---	--




22	 VA-D45 X30	
----	--	--







25



VA-B24
X1



PPX4
X2









VA-D44
X4



VA-D45
X28



VA-D46
X2



26



VA-C27
X3



VA-C28
X4





VA-C29
X1




PB7C
X2




VA-D44
X28



a



b



c

27











CN-A30
X4




VA-40
X1



VA-D44
X35



28



VA-36
X2



VA-37
X4



VA-32R
X2










VA-32L
X2



VA-D44
X60



VA-D48
X4



29



PPX5
X2



VA-38a
X2
















VA-38b
X2



VA-39
X2



VA-D49
X8



30



W1
X2



W2
X2






PPX10
X2



VA-51
X2



VA-D44
X20



31




DVA-3
x6









DVA-4
x1



VA-D49
x12



x2



23

Responsable de la commercialisation du produit / Company in charge of commercializing the product / Responsable de la comercialización del producto / Responsabile della commercializzazione del prodotto:

GECODIS SA

32, rue de paradis

75010, Paris, France

Service commercial/ Commercial service/ Servicio comercial / Servizio commerciale :

Habitatetjardin.com

32, rue de paradis

75010, Paris, France

Assistance : +33 (0) 1 47 70 33 64

Service après-vente/ After sale services/ Servicio post-venta / Servizio dopo vendita:

GECODIS SA

32, rue de paradis

75010, Paris, France

<http://sav.habitatetjardin.com>