








An icon showing an L-shaped metal bracket inside a circle, and a power drill with a diagonal line through it, indicating that a drill should not be used.	A warning triangle containing an exclamation mark.	A circular clock face with tick marks around the perimeter.
		<b>30'</b>
An icon showing a rectangular block being lifted from a surface by a hand, and another block being lifted by a hand with a diagonal line through it, indicating that lifting should be done correctly.	A warning triangle containing an exclamation mark.	A simple line drawing of a person.
		<b>2</b>

<b>A</b>	<b>B</b>	<b>C</b>	<b>D</b>	<b>E</b>
		 M6 x 15		
<b>x 1</b>	<b>x 4</b>	<b>x 12</b>	<b>x 12</b>	<b>x 1</b>






**A**



**B x 4**



1

<p>A</p>  <p>x 1</p>	<p>B</p>  <p>x 4</p>	<p>C</p>  <p>M6 x 15</p> <p>x 12</p>	<p>D</p>  <p>x 12</p>	<p>E</p>  <p>x 1</p>
---	---	---	--	---

